# COMPLETION REPORT

| | | |
|---|---|---|
| 1 | Name of the Work | Improvements and Asphalting to Chikkasandra main road from Hesaraghatta main road to Vigneswara Layout in ward no 12 Shettyhalli Sub Division. |
| 2 | Sanctioned Estimate No. and date | BBMP/CE/DZ/TS/1169/18-19 Dated: 20.02.2019. |
| 3 | Head of Account which is chargeable | Job Code 012-19-000057 |
| 4 | Instrument Order No. and date | EE/DD/WO/ 358 /19-20 dated: 27.02.2019 |
| 5 | Name of Contractor | M/s Technical Manager(West), KRIDL |
| 6 a | Time Stipulated for Completion of Work | 180 days |
| b | Delay in Execution of Work | |
| 7 | Measurement recorded in | MB No: 3474/2018-19 Page No: 3474369 to 3474371 |
| 8 | Check Measurement of the Asst | |
| 9 | Name of the office/official in charge of the work | |
| 10 | a) Asst. Eng/Junior Engineer | A.P. Shivakumar, A.E |
| | b) Asst. Executive Engineer | Jayalingappa .B.L, AEE |

| Sanctioned Estimated Amount | Amount Claims as per actually Vide as per bills | Excess | Savings |
|---|---|---|---|
| Rs. 200.00 Lakhs | Rs. 1,96,15,690.85 1961338₹:- | - | 386623 =- |

1. Certified that the above has been completed within the stipulated time noted in the
2. Certified that the contractor has delayed and completed the work for which necessary fine recovered
3. Certified that the above work has been executed by the contractor satisfactory in

Assistant Engineer
Ward no.12

Asst.Executive Engineer
Shettyhalli sub division

Executive Engineer
Dasarahalli Division

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

Received the sum of Rs. 1,96,15,690.85 (Rupees one lakh ninety six lakhs fifteen thousand six hundred ninety only) in full towards the above completed work. I do further promise not to prefer any claim in respect of the above work after receipt of the above amount.

ಗುತ್ತಿಗೆದಾರರು ಮೇಲ್ಕಂಡ ಕಾಮಗಾರಿಗೆ ಸಂಬಂಧಪಟ್ಟಂತೆ ಮೇಲ್ಕಂಡ ಮೊತ್ತವನ್ನು ಪೂರ್ಣ ತೃಪ್ತಿಯಾಗಿ ಸ್ವೀಕರಿಸಿದ್ದು, ಇನ್ನೂ ಯಾವುದೇ ಹಣ ಬರಬೇಕಾಗಿರುವುದಿಲ್ಲವೆಂದು ಹಾಗೂ ಈ ಕಾಮಗಾರಿಗೆ ಸಂಬಂಧಪಟ್ಟಂತೆ ಯಾವುದೇ ಕ್ಲೇಮುಗಳನ್ನು ಸಲ್ಲಿಸುವುದಿಲ್ಲವೆಂದು ಪ್ರಮಾಣೀಕರಿಸಿದೆ.

Scanned by CamScanner